

EML 2322L Quiz 10 (10/29/19)

Answer the following questions based on the information presented in class. You can use **your** notes but do not speak with others.

What is the equation governing maximum peripheral tool velocity as a function of tool size?

$$V = \pi \times \underline{\hspace{1cm}} \times \underline{\hspace{1cm}}$$

What is the purpose and benefit of peck drilling?
peck drilling help chips _____
so they don't collect inside the hole and cause the drill bit to _____, seize and break

What is the limiting factor for how fast a drill or endmill can rotate in a particular material?

- maximum speed of machine spindle
- type of taper/collet used to hold tool
- number of flutes on the cutter
- heat generated in the cutting zone
- other: _____

What is the limiting factor for how fast a drill or endmill can feed (or advance) thru any material?

- maximum speed of machine spindle
- operator courage
- phase of the moon at that particular hour
- size / strength of cutting edges / lips
- other: _____

What is the limiting factor for how deep to cut (per pass) with an endmill in a particular material (assuming sufficient flute length)?

the limiting factor is cutting tool / workpiece / machine _____ (which must resist the cutting forces and subsequent vibrations)

Select six factors that affect optimum cutting speed for drilling and milling:

- strength & thermal conductivity of material
- depth of hole
- presence and efficiency of cutting fluid
- type, condition & stiffness of cutting machine
- stiffness of workpiece, fixture and tooling
- quality of holes desired
- whether you pay for replacement tools ☺

Name: _____

Lab Period: T5-6 / T7-8 / T9-10
(circle one) W2-3 / W4-5 / W7-8 / W9-10
R2-3 / R4-5 / R7-8 / R9-10

Based on lecture notes, circle the conditions under which you would use lower cutting speeds:

- heavy (roughing) / light (finishing) cuts
- when cutting stronger / weaker materials
- to minimize / maximize tool life
- when cutting flexible / rigid workpieces

Calculate the spindle speed [rpm] and feedrate [in/min] for a 1/2 inch HSS drill bit in mild steel (0.2-0.3 C) when using a manual milling machine:

from Table 1: $V \approx \underline{\hspace{1cm}}$ ft/min
 $N = 12 \text{ in/ft} \times V \text{ ft/min} / (\pi \times D \text{ in/rev})$
 $N = 12 \text{ in/ft} \times \underline{\hspace{1cm}}$ ft/min / $(\pi \times \underline{\hspace{1cm}}$ in/rev)
 $N = \underline{\hspace{1cm}}$ rpm

from Table 2: $f_r \approx \underline{\hspace{1cm}}$ in/rev
 $f = N \text{ rev/min} \times f_r \text{ in/rev}$
 $f = 764 \text{ rev/min} \times \underline{\hspace{1cm}}$ in/rev = $\underline{\hspace{1cm}}$ in/min
 scale back 60%: $N \approx \underline{460 \text{ rpm}}$, $f \approx \underline{3.7 \text{ in/min}}$

Calculate the spindle speed [rpm] and feedrate [in/min] used when milling an aluminum part with a 1/2 inch diameter, 2 flute HSS endmill on a manual milling machine in lab.

from Table 1: $V \approx \underline{\hspace{1cm}}$ ft/min
 $N = 12 \text{ in/ft} \times V \text{ ft/min} / (\pi \times D \text{ in/rev})$
 $N = 12 \text{ in/ft} \times \underline{\hspace{1cm}}$ ft/min / $(\pi \times \underline{\hspace{1cm}}$ in/rev)
 $N = \underline{\hspace{1cm}}$ rpm

from Table 3: $f_t \approx \underline{\hspace{1cm}}$ in/rev
 $f = N \text{ rev/min} \times f_t \text{ in/tooth} \times m \text{ teeth/rev}$
 $f = 1910 \text{ rev/min} \times \underline{\hspace{1cm}}$ in/tooth $\times \underline{\hspace{1cm}}$ teeth/rev
 $f = \underline{\hspace{1cm}}$ in/min
 scale back 60%: $N \approx \underline{1150 \text{ rpm}}$, $f \approx \underline{9.2 \text{ in/min}}$

What size clearance hole would you specify for a mounting bracket that uses M6x1.0 fasteners in (A) aluminum using loose tolerances or (B) steel using more precise tolerances?

- _____
- _____