

EML2322L – MAE Design and Manufacturing Laboratory

TA Outline (Lathe & Mill Training)

- Remind students to sign in the attendance roster **in the proper location**
- Improper Shoes: students receive an ‘S’ next to their name in roster; return for another lab
- No Safety Sheets: students receive an ‘SS’ next to their name in roster; provide a lab copy
- No Long Pants: students receive a ‘P’ next to their name in roster; return for another lab
- Student work groups are not yet assigned
- Split class in half: 2 groups train on mill, 2 groups train on lathe; then switch.
- Safety glasses required; aprons optional
- Remove **ALL** jewelry, watches & bracelets; tuck in or remove loose clothing; tie hair back

Lathe Training

- A. Basic machine operation and nomenclature:
 - X & Z-axes, spindle, chuck, headstock, tailstock, carriage, cross slide, tool post, tool holder (**students should know this from the HW so ask for their participation**)
 - DRO on all axes are graduated in thousands of an inch; everything in this shop is in thousandths, so start thinking in thousandths; **typical laser printer paper is .003"**
 - machine safety: not a workbench; tools fall off carriage and headstock
- B. Clamping the workpiece
 - chuck safety: **CHUCK KEY**; placing spindle in neutral; protruding jaws (NEVER reach around chuck); clamp on at least 1" of material; explain cutting zone; leave space around operator
- C. Clamping and setting up the tool
 - rotate tool post; show tip of carbide cutting insert; set relief angles (~5°) for facing/turning; use plastic ruler for height setup (ALWAYS on center); **rotate chuck by hand to check clearance**; mark workpiece with sharpie to ensure you don't cut too close to the chuck jaws
- D. Selecting speed & turning machine on:
 - Select HI/LO range with machine off; typically use HI but make sure speed control is set to the LOW end of the range (2-3 on the knob)
 - Ensure spindle rotates CCW as viewed from tailstock; rotate spindle switch CCW as well
- E. Cutting
 - touch off GENTLY using RH rule; zero DRO; take off 0.020" in TURNING & FACING
 - demonstrate use of power feeds: controls levers; reversing direction
 - everyone participates in the manual & power cutting procedures outlined above
 - while students do this, review the safety sheet and cover the rest of the rules about the lathe you missed up to this point: i.e. **keep hands out of the cutting zone, 0.100" max. depth of cut on the RADIUS, never grab or remove chips by hand, proper filing technique**, etc.
- F. Cleanup (SPOTLESS—we can never expect better than they see during this training session); **DEMAND students pull out and push in chip trays GENTLY**; careful with corners on machines during cleaning; spray rags, not machines; **TRY NOT TO wipe off guideways with cleaner or rag, as that removes the oil which is crucial for proper lubrication**

Milling Machine Training

- A. Basic machine operation and nomenclature:
 - X, Y & Z-axes; spindle; tool mounts in spindle; part mounts in vise and moves around
 - DRO on all axes are graduated in thousands of an inch; everything in this shop is in thousandths, so start thinking in thousandths; **typical laser printer paper is .003"**
 - table safety: not a workbench, tools roll off, never cover tools w/rags
- B. Discussion of tools/tool safety
 - Show tool; identify cutting edges & shank; proper handling w/rag, show chipped cutter
- C. Installing & removing tools (1 TA talks, 1 TA shows; everyone either installs or removes tool)
- D. Clamping workpieces:
 - Explain how to align parts in vise; show parallels in boxes; **show different heights**
 - Clean vise before using; always move rag/hand **away** from cutter
 - Clean parallels before using because **they are slippery and dropped easily**
 - Explain the parallels are **PRECISION** tools and to be treated as such. Don't leave them sitting on the tables, place them back in the box when not in use. **NEVER drop them in the vise but gently lower them into position.**
 - Apply ~5 lb force to vice handle; use a plastic hammer to tap workpiece into full contact with parallels; then apply ~40 lbs on vice handle; remove parallels; remove vise handle
 - **Never run the cutter into the vise or bring it into extremely close proximity**
- E. Selecting speeds & turning machine on:
 - Select HI/LOW range with machine turned off; **TAs only during entire semester**
 - ON/OFF switch: direction matches range, **never flip into reverse w/o stopping spindle**
 - Turning spindle on: **safe starting distance from workpiece, verify CW rotation every time, adjust spindle speed while machine is running**
- F. Manual cutting:
 - Lock spindle clamp; touch off on workpiece **very gently (get down at eye level w/bottom of tool)**
 - zero Z axis; show vernier dial and locking nut; explain each graduation is 0.001"
 - move off part (**show and emphasize RH rule**); set depth of cut in air (.010")
 - **ramp gently into workpiece w/ hand on table**; increase feedrate while hand is on table
 - demonstrate use of power feed: speed knob to 0; select joystick direction; ramp gently into contact and across workpiece w/hands on table & joystick; set knob back to zero; put power feed joystick in neutral; **NEVER switch direction without completely stopping table**
 - everyone participates in the manual cutting procedures outlined above; demonstrate power feed, focusing on safety; allow students to cut using the power feed **if time allows**
 - while students do this, review the safety sheet and cover the rest of the rules about the mill you missed up to this point: i.e. **keep hands out of the cutting zone, 0.100" max. depth of cut, don't remove chips by hand**, never leave a running machine unattended for any reason, etc.
- G. Cleanup (SPOTLESS—we can never expect better than they see during this training session); careful with corners on machines during cleaning; spray rags, not machines; **TRY NOT TO wipe off guideways with cleaner or rag, as that removes the oil which is crucial for proper lubrication**
 - During the training make sure students are highlighting the most important points in the safety sheets so you keep their attention. **Make an example of anyone not following along.**
 - Make sure students understand the difference between the pneumatic controls & the power switch.