Low-Velocity Impact Damage in Graphite-Epoxy Laminates Subjected to Tensile Initial Stresses

Bhavani V. Sankar* Bradley University, Peoria, Illinois and C.T. Sun† Purdue University, West Lafayette, Indiana

Abstract

L OW-VELOCITY impact tests in the velocity range of 10-40 m/s were conducted with graphite-epoxy laminated beams as targets. In some of the tests the beams were subjected to tensile initial stresses. The delamination area was measured by ultrasonic C-scanning. The damage was characterized by the reduction in tensile strength and by the delamination area. It was found that tensile initial stresses reduce the threshold impact velocity for damage, but beyond certain impact velocity they may help in containing delamination.

Contents

The presence of tensile stresses in beams or plates gives rise to an apparent stiffening effect that reduces the incremental deformation. On the other hand, the initial stress combined with incremental stress may cause more damage in the structures.

In the present experimental study low-velocity impact tests in the velocity range of 10-40 m/s were conducted with SP313 graphite-epoxy laminated beams as targets, and a 12.5 mm diameter steel ball as the impactor. Some of the specimens were under tensile initial stresses during impact. The laminate configuration was $[0_2/90_2/0_2/90_2/0_2]_s$. Specimens of 38 mm width were held between two rigid clamps and the initial stresses were applied by pulling the clamps apart using a pneumatic cylinder. The effective span of a specimen was 180 mm. The impactor was propelled by a sudden release of pressurized air into the delivery tube. The velocity was computed from the travel time of the projectile between two photodetectors mounted on the delivery tube.

We assumed that an impacted specimen has suffered damage if there was any delamination detectable by ultrasonic C-scanning or if there was a reduction in the ultimate tensile strength. The threshold velocity for damage was defined as the minimum impact velocity required to initiate damage in the specimen. Because of the wide scatter in experimental data, precise determination of the threshold velocity may require a larger number of specimens. So, the best estimate of threshold velocity that did not cause any damage and the minimum velocity that caused some damage. The ultrasonic C-scanning technique measured the damage to the front, middle, and back side of the specimen. The damage levels in a specimen were coded with numbers 0-9. Thus, a 0 in the digital output (Fig. 1) represents an area of 0.75×0.75 mm in the specimen where

Received Sept. 6, 1984; synoptic received May 20, 1985. Copyright © American Institute of Aeronautics and Astronautics, Inc., 1985. All rights reserved. Full paper available from AIAA Library, 555 W. 57th St., New York, NY 10019. Price: microfiche \$4.00; hard copy \$9.00. Remittance must accompany order.

*Assistant Professor of Mechanical Engineering. Member AIAA. †Professor of Aeronautics and Astronautics. Associate Fellow AIAA. there is no damage. A 9 indicates maximum damage within that specimen.

There were two types of cracks readily visible after impact. There was always a single longitudinal crack on the back surface symmetric about the impact point. The length of the crack varied 10-50 mm. This splitting of 0 deg layer was assumed to be caused by the σ_{yy} stresses due to platelike behavior of the laminated beam during impact. (Note: The laminate was assumed to be in the xy plane with the longitudinal axis of the beam parallel to the x axis.) The second set of cracks were on the impact side. Two parallel longitudinal cracks were observed on either side of the impact point. They were separated by about 5 mm. Such splitting occurred only at higher impact velocities.

Another interesting observation was made about the shape of the delamination areas. From the C-scan results, it was found that a damage area on the front side (impact side) was always on either side of the longitudinal axis of symmetry. A representative C-scan output is shown in Fig. 1. On the front side, the damage along the longitudinal centerline was nil or minimal in some cases, whereas on the back side there were two damage areas on either side of the transverse line of symmetry. In the middle layers, there were delaminations in all four quadrants, but the shapes were closer to that in the back

112222 11223 11233 1	1122223322222221111	000000000000000000000000000000000000000
112256577555121211 122557583777721111 122557583777721111 10000024577000007755220000 122577775207011 12257778537777512222 11201015507772011001 1122010020212122221 1122010021012122221 1122010021012122221 1122010021012122221 1122010021012122221 1122010021012122221 1122010021012122221 1122010021012122221 1122010021012122221 1122010021012122221 1122010021012122221 1122010021012122221 1122010021012122221 1122010021012122221 1122010021012122221 112201002001202222 112201001001001202222 10000000000	112222	000000000000000000000000000000000000000
122 55 57 5 5 7 7 7 7 2 2111 12 7 7 7 8 5 3 7 7 7 7 2 2111 12 1 3 5 6 7 7 7 7 20 1 1 1 0 12 1 3 5 6 7 7 7 7 20 1 1 1 0 12 1 3 5 6 7 7 7 7 20 1 1 1 0 11 0 1 0 1 1 0 1 0 1 0 1 0 11 1 2 1 0 3 6 7 7 7 20 1 1 0 0 11 1 2 0 1 0 7 1 0 1 0 1 0 0 11 2 2 1 0 3 0 2 2 2 2 1 1 0 3 5 0 9 7 9 7 4 0 0 0 5 6 0 7 3 3 5 5 3 5 0 11 2 2 1 0 0 0 1 0 1 2 2 2 2 1 0 0 3 5 5 7 7 5 0 0 0 0 7 7 9 7 9 3 3 5 3 0 0 11 2 2 0 1 0 0 1 0 1 2 2 2 2 1 0 0 3 5 5 7 7 5 0 0 0 0 7 7 8 7 3 8 0 0 0 11 2 2 0 1 0 0 1 2 0 2 2 2 2 1 0 0 0 7 7 0 9 7 9 3 4 0 0 0 5 6 0 7 3 3 6 5 3 3 5 0 0 11 2 2 0 1 0 0 1 0 1 2 2 2 2 1 0 0 0 7 0 7 9 7 9 7 4 0 0 0 5 5 6 0 7 8 3 7 3 5 3 0 0 11 2 2 0 1 0 0 1 0 0 1 2 0 2 2 2 0 0 0 5 7 0 5 5 6 5 1 0 0 0 0 7 7 3 7 3 2 0 0 0 10 0 1 2 0 0 1 1 0 1 2 0 0 2 2 0 0 0 1 3 5 5 5 7 5 0 0 0 0 0 1 0 7 3 2 2 0 0 0 10 0 0 1 0 1 0 3 7 0 0 2 1 0 0 10 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	1122345577635 21211	000000000000000000000000000000000000000
12 67783337 211111 0000224577300005027937320000 12 13657772007011 0257830050000250033543000 00002507330000 0000007772011001 0257830050000250033543000 000050033543000 000050033543000 0010017720100100 04478883930400005703338053000 000055003338053000 000055078338053000 112010021012122221 00057005400000550030005327052 00005500300000000000000000000000000000	122 557383777 2111	00000 22353 0000000278522 0 0000
12 1356777/2007011 0235789087,0000560833541,000 00010017720111001 0134789995,00007999933,3503 011100101510101100 04478889904,000057069336,000 11220100302222111 013079995,000055069338,000 1122010010101202222 0037009705,0005778838,000 2222011001001001202222 0005555750000,000778808743603 2222011001001001202222 00005555750000,000778808743603 0000100000000000000000000000000000000	12 577883375 211111	0000224577 0000002703732 000:
0:000000 77720111001 01347379994500007799793435051 0:0111001710010100 04738899440000789379343053 0:112201002102222111 013507997840000570693994000 1:122010021012122221 0003709705400007799783053100 0:021012122221 00037097054000077897830070 0:021012122221 00037097054000077897830070505000000000000000000000000000000	12 356777 2000011	0 235789005 000 2608 9854 3 00:
0011110167101001100 004788899045000057089399030 111001015710101100 004788899045000057089399030 11122100302222111 003509997410005500938053000 1122210030122221 00370970540004778808743603 223001001031202222 0025705565000000000000000000000000000000	000000577720111001	0,3478999964,000679999885320;
11100101010101010 0+4589990510005570693990000 11221003002222111 013099970540005570693990000 12201001001001202222 002570555510000 222010001001001202222 000000000000000000000000000000000000	001111015710101100	0\$47888990470000\$788938853203
111222100302222111 1122010021012122221 222010001001202222 2222211011012002221 00037097055 0000778808743003 222221011012002221 000000110000000000	1110010157101011100	0245899900520002570893994000
1122010021012122221 00037009705410004778808743603 2220010001031202222 002570556300000030073220000 22221101101200223 00000012000000000000000000000000000000	1112221003032222111	0 1 3509998741000(5500988053)0:
2220010001001202222 002570556510000003073220000 2222211010120002223 000000000000000000000000000000000000	1122010021012122221	00237009705420004778808743203
2222211011012002223 000001555750000000073220000 00210220111222011 0000000110000000000000000000000000000	2220010001001202222	00 2570556510000 03800532/00:
002102201112222011 00000001200000000000000000000000000000	2222211011012002223	0000 356575200003 0973222000
161122016 03223033 000000000000000000000000000000000000	002102202112222011	000000000000000000000000000000000000000
00001101/97100070011 Back 122 5569972000111 Back 122 5569972000111 000000000000000000000000000000000000	101122016 000220000	00000000000000000000000000000000000000
GG030107710030011 Back 12275509772000111 000000000000000000000000000000000000	000011028900021000	000000000000000000000000000000000000000
122 122 000000000000000000000000000000000000	660890 999 10009911	Back
123 123 1232 <	122 23530957 2000111	
2221 55777775 5222 57577775 52222 57577775 52222 57577775 52222 57577775 52222 57577775 52222 57577775 52222 57577775 52222 57577775 57577775 57577775 52222 57577775 57577775 5757775 57577775 5757775 5757775 57577775 57577775 57577775 57577775 57577775 57577775 57577775 57577775 57577775 57577775 575777775 575777775 575777775 575777775 575777775 575777775 57577775 57577775 575777775 575777775 575777775 575777775 575777775 575777775 575777775 575777775 575777775 575777775 575777775 575777775 5757777775 5757777775	12313777835 211222	000000000000000000000000000000000000000
222223 0000000111100000000 222223333332222222 0000000111100000000 222223333332222222 000000111100000000 Front 0000000111100000000 10150000000000000000000000000000000000	222 315511111 22222	0 0000000000000000000000000000000000000
22222233333332222222 00000000111100000000 Front 0000000100000000000000000000000000000	22222 3131113 22222	0000000111110000000
Front 000000000000000000000000000000000000	22222233333322222222	900000001111000000000
Profit 00-0000000000000000000000000000000000	Eront	000000001111000000000
00%000%00%00%311000 1970166000%5311000 197112593500%59852100 00%135871003788512000 197012100%173190000 Middle jm00m000%2100000000 00%00000%21000000000 00%00000%11100000000 00%00000%11000000000 00%00000%110000000000	From	000000000000000000000000000000000000000
1010 JULE COURCESSITION 1011 JULE COURCESSITION 1011 JULE COURCESSITION 1011 JULE COURCESSITION 1011 JULE COURCESSITION 1011 JULE COURCESSITION 1010 JULE COURCESSITI		00"000 000000 411000
Middle 1000000000000000000000000000000000000		101200160000258311100
Middle in roomaar 2000 1000 - 2000 Middle in roomaar 2000 1000 - 2000 Middle in roomaar 2000 1000 - 2000		11211149133375534111333
Middle jnnon 2000 1000000000000000000000000000000000		11:1125956001599852100
Middle jnnoonaar jast 3000 30 01 - 1 - 1 - 0 - 0 - 1 - 1 - 0 - 0 - 0		1001125871003788512000
Middle inconcorr, one 2100000 0000000000000000000000000000000		1020 024 0000 786 0000
		Middle 1000000000000000000000000000000000000
		101000001210000000
		222020202222000000000
		11100000000
00000000000000000000000000000000000000		1000000111110000000
50000000000000000000000000000000000000		2000000011110000000
000000000000000000000000000000000000000		000000000000000000000000000000000000000
		000000000000000000000000000000000000000

Fig. 1 C-scan digital output.





Fig. 2 Effect of initial stresses on the residual strength.

Table 1 Threshold impact velocities for different types of damage

	Threshold velocity, m/s	
Types of damage	Preload = 0 kN	Preload = 22 kN
Delamination in the front portion (i.e., impact side)	22.5	18.8
Delamination in the middle and back portions	22.5	16.2
Reduction in tensile strength	22.5	18.8

side in two out of three cases. The consistency of these shapes in most of the specimens gave us confidence in our ability to map the delaminations at different depths using ultrasonic Cscanning. It should be noted that the shapes shown in Fig. 1 correspond to an impact velocity close to the threshold velocity. At higher velocities, the delaminations spread in all directions.

Two sets of impact tests were conducted, one without any preload and the other with a preload of 22 kN, which was about one-third of the ultimate strength of virgin specimens. Table 1 gives the threshold velocities for different types of damage. The results of C-scanning were as follows. The damage area in the front side was always larger in the presence of initial stresses. However, the damage areas in the middle and back portions showed a different behavior. In the velocity range of 16-30 m/s, the damage areas in the middle and back portions were larger in the initially stressed beam. Beyond 30 m/s, the damage area started decreasing in the presence of initial stresses and the area of damage was less in the prestressed beams.

The residual tensile strength of impacted specimens is given in Table 2. Because the specimens were cut from different

1

	Preload.	Impact velocity.	Ultimate strength
Panel No.	kN	m/s	kN
1	0	0	80.7(100) ^a
	0	26.8	64.5(80)
	0	30.3	49.5(61)
	0	34.2	53.4(66)
	22	27.4	60.1(75)
	22	31.4	53.4(66)
	22	33.9	49.0(61)
2	22	9.1	60.1(98)
	22	14.8	62.7(102)
	22	20.0	59.6(97)
	22	26.9	48,5(79)
	22	26.2	55.6(91)
3	0	0	72.3(100)
	Ō	32.7	52.4(73)
	Ō	34.2	55.6(77)
	22	29.8	57.9(80)
4	0	0	71.2(100)
	0	20.6	72.3(102)
	0	33.3	61.2(86)
	22	20.4	64.7(91)
5	0	0	72.9(100)
	0	25.6	69.5(95)
	0	28.6	68.1(93)
	0	36.3	52.8(72)
	22	26.1	51.7(71)
	22	28.3	46.1(63)
	22	35.1	0.(0)
6	0	0	72.9(100)
	0	31.3	45.6(63)
	0	33.0	56.7(78)
	22	18.8	72.9(100)
	22	23.2	60.5(83)
	22	28.0	59.7(82)

^aNumbers in parentheses are residual strength as the percentage of strength of virgin specimens.

panels, there was scatter in the data. So, the residual strength values were expressed as the percentage of tensile strength of virgin specimens cut from the corresponding panel. This is plotted in Fig. 2. It is seen that the initial stresses cause more reduction in strength than in the specimens impacted without initial stresses. This suggests that strength reduction may be due to fiber breakage during impact.

In the tension tests, specimens impacted under preload suffered a clean cut at the impact point. There was not much delamination and it resembled the failure of virgin specimens, whereas the specimens impacted without any preload showed more delamination in the impact area after failure in the tension tests.